

2022 November Outages

Outage	Time Off	Time On	Duration	# Out	Sub	Feeder	Phs	Cause Desc	Equip Desc
200796	10/30/2022 15:53	11/1/2022 12:29	44:35:00	1	09-Staunton Sub	1	B	LIGHTNING	TRANSFORMER BAD
200809	11/1/2022 11:00	11/1/2022 12:05	1:05	3	02-Bunker Hill Sub	5	C	MAINTENANCE	POLE, DISTRIBUTION
200827	11/1/2022 17:37	11/1/2022 19:05	1:27	29	12-Newbern Sub	1	A	UNKNOWN	FUSE CUTOUT
200812	11/2/2022 6:30	11/3/2022 9:02	26:32:00	49	13-Honey Bend Sub	99	ABC	MAINTENANCE	TRANSMISSION SUBSTATIONS
200810	11/2/2022 7:00	11/4/2022 11:19	52:19:00	57	10-Taylor Springs Sub	2	ABC	MAINTENANCE	TRANSMISSION SUBSTATIONS
200811	11/2/2022 7:30	11/4/2022 10:39	51:09:00	293	10-Taylor Springs Sub	3	ABC	MAINTENANCE	TRANSMISSION SUBSTATIONS
200838	11/2/2022 10:42	11/2/2022 11:26	0:44	46	08-Rinaker Sub	7	ABC	Machinery	ANCHOR OR GUY
200839	11/2/2022 20:05	11/2/2022 20:05	0:00	0	11-Womac Sub	7	A	UNKNOWN	NO EQUIP CODE
200840	11/3/2022 1:40	11/3/2022 3:31	1:51	1				PUBLIC ACCIDENTS, OTHER	FUSE CUTOUT
200843	11/3/2022 10:06	11/3/2022 14:44	4:38	0	02-Bunker Hill Sub	1	C	MEMBER CAUSED	TRANSFORMER, DISTRIBUTION
200847	11/3/2022 11:12	11/3/2022 11:12	0:00	0	13-Honey Bend Sub	7	A	UNKNOWN	MEMBERS SIDE
200846	11/3/2022 11:12	11/3/2022 11:12	0:00	0	13-Honey Bend Sub	7	ABC	UNKNOWN	MEMBERS SIDE
200848	11/3/2022 11:22	11/3/2022 11:22	0:00	0	13-Honey Bend Sub	7	A	UNKNOWN	MEMBERS SIDE
200849	11/3/2022 11:45	11/3/2022 11:45	0:00	0	13-Honey Bend Sub	7	C	UNKNOWN	MEMBERS SIDE
200858	11/4/2022 13:48	11/4/2022 15:38	1:50	1	07-Palmyra Sub	1	C	CONNECTIONS	METER OR METER LOOP
200864	11/4/2022 13:54	11/4/2022 14:35	0:41	17	01-Brighton Sub	7	A	MAINTENANCE	FUSE CUTOUT
200866	11/4/2022 20:18	11/4/2022 22:32	2:13	1	06-Nutwood Sub	3	C	UNKNOWN	FUSE CUTOUT
200869	11/4/2022 20:37	11/4/2022 21:23	0:46	2	12-Newbern Sub	1	A	UNKNOWN	CONNECTOR OR CLAMP
200887	11/4/2022 21:54	11/5/2022 0:21	2:26	121	02-Bunker Hill Sub	1	A	TREES, OTHER	OCR OR SECTIONALIZER
200936	11/5/2022 5:08	11/5/2022 7:15	2:06	7	06-Nutwood Sub	1	C	UNKNOWN	FUSE CUTOUT
200944	11/5/2022 6:21	11/5/2022 8:30	2:08	24	03-Butler Sub	1	A	TREES, OTHER	OCR OR SECTIONALIZER
200953	11/5/2022 7:13	11/5/2022 11:45	4:31	25	11-Womac Sub	1	B	TREES, OTHER	NO EQUIP CODE
200958	11/5/2022 8:43	11/5/2022 10:25	1:41	6	11-Womac Sub	3	C	TREES, OTHER	DEFAULT EQUIPMENT
200960	11/5/2022 9:12	11/5/2022 11:00	1:48	1	02-Bunker Hill Sub	3	C	TREES, OTHER	OVERHEAD SECONDARY CONDUCTOR
200963	11/5/2022 9:32	11/5/2022 12:10	2:38	1	11-Womac Sub	1	A	AGE OR DETERIORATION	FUSE CUTOUT
200986	11/5/2022 9:56	11/5/2022 12:00	2:03	33	09-Staunton Sub	7	B	Animals	OCR OR SECTIONALIZER
200978	11/5/2022 10:03	11/5/2022 12:00	1:57	1	09-Staunton Sub	7	C	Animals	OCR OR SECTIONALIZER
200987	11/5/2022 10:09	11/5/2022 10:09	0:00	0	09-Staunton Sub	7	C	UNKNOWN	MEMBERS SIDE
200989	11/5/2022 10:13	11/5/2022 11:57	1:44	1	09-Staunton Sub	7	A	Animals	OCR OR SECTIONALIZER
200994	11/5/2022 10:27	11/5/2022 13:15	2:47	2	08-Rinaker Sub	5	B	TREES, OTHER	FUSE CUTOUT
201014	11/5/2022 11:44	11/5/2022 14:20	2:35	74	05-Jerseyville Sub	2	A	TREES, OTHER	OCR OR SECTIONALIZER
201022	11/5/2022 13:10	11/5/2022 16:50	3:40	52	06-Nutwood Sub	5	A	TREES, OTHER	OCR OR SECTIONALIZER
201028	11/5/2022 13:23	11/5/2022 16:14	2:50	2	12-Newbern Sub	1	A	TREES, OTHER	FUSE CUTOUT
201025	11/5/2022 13:25	11/5/2022 22:07	8:42	5	11-Womac Sub	5	B	TREES, OTHER	OVERHEAD PRIMARY CONDUCTOR
201029	11/5/2022 13:38	11/5/2022 14:46	1:08	0	07-Palmyra Sub	1	C	MEMBER CAUSED	MEMBERS SIDE
201031	11/5/2022 15:33	11/5/2022 16:02	0:29	1	11-Womac Sub	5	B	UNKNOWN	NO EQUIP CODE
201033	11/5/2022 16:29	11/5/2022 16:33	0:04	1	12-Newbern Sub	1	A	UNKNOWN	FUSE CUTOUT
201034	11/5/2022 16:32	11/5/2022 16:32	0:00	0	08-Rinaker Sub	5	C	UNKNOWN	MEMBERS SIDE
201035	11/5/2022 18:20	11/5/2022 18:20	0:00	0	02-Bunker Hill Sub	1	C	UNKNOWN	MEMBERS SIDE
201036	11/5/2022 18:43	11/5/2022 18:43	0:00	0	02-Bunker Hill Sub	1	C	UNKNOWN	MEMBERS SIDE
201038	11/6/2022 9:40	11/6/2022 10:58	1:18	1	05-Jerseyville Sub	6	A	TREES, OTHER	FUSE CUTOUT
201089	11/7/2022 12:45	11/7/2022 14:59	2:14	33	01-Brighton Sub	7	A	TREES, OTHER	OVERHEAD PRIMARY CONDUCTOR

201092	11/7/2022 15:23	11/7/2022 15:35	0:12	33	01-Brighton Sub	7	A	Frayed/Broken Strands	FUSE CUTOUT
201143	11/8/2022 13:08	11/8/2022 15:04	1:56	17	02-Bunker Hill Sub	5	A	UNKNOWN	FUSE CUTOUT
201181	11/9/2022 2:51	11/9/2022 2:51	0:00	0	04-Witt Sub	1	B	UNKNOWN	POLE, DISTRIBUTION
201232	11/9/2022 16:31	11/10/2022 16:31	24:00:00	0	05-Jerseyville Sub	2	A	EQUIPMENT	MEMBERS SIDE
201306	11/10/2022 13:44	11/10/2022 15:12	1:28	95	09-Staunton Sub	5	ABC	PUBLIC ACCIDENTS, OTHER	OVERHEAD PRIMARY CONDUCTOR
201316	11/10/2022 14:10	11/10/2022 16:47	2:36	38	10-Taylor Springs Sub	3	C	MEMBER CAUSED	OCR OR SECTIONALIZER
201326	11/10/2022 15:48	11/10/2022 17:20	1:31	42	09-Staunton Sub	1	C	PUBLIC ACCIDENTS, OTHER	OCR OR SECTIONALIZER
201331	11/11/2022 3:50	11/11/2022 6:04	2:14	1				FIRE	NO EQUIP CODE
201382	11/12/2022 16:42	11/12/2022 16:45	0:03	1	02-Bunker Hill Sub	1	C	UNKNOWN	MEMBERS SIDE
201384	11/12/2022 19:47	11/12/2022 19:55	0:08	0	08-Rinaker Sub	5	B	UNKNOWN	NO EQUIP CODE
201432	11/13/2022 8:01	11/13/2022 8:50	0:48	0	02-Bunker Hill Sub	5	B	UNKNOWN	MEMBERS SIDE
201489	11/13/2022 14:19	11/13/2022 15:25	1:06	20	02-Bunker Hill Sub	1	C	UNKNOWN	FUSE CUTOUT
201490	11/13/2022 14:37	11/13/2022 15:25	0:47	2		2	99	C UNKNOWN	FUSE CUTOUT
201538	11/14/2022 10:16	11/14/2022 15:49	5:32	17	01-Brighton Sub	1	C	Machinery	POLE, DISTRIBUTION
201539	11/14/2022 15:48	11/15/2022 13:00	21:11	1	01-Brighton Sub	1	C	Machinery	POLE, DISTRIBUTION
201549	11/14/2022 18:29	11/14/2022 21:13	2:44	12	11-Womac Sub	5	A	PUBLIC ACCIDENTS, OTHER	POLE, DISTRIBUTION
201586	11/15/2022 11:47	11/15/2022 12:10	0:22	3	01-Brighton Sub	1	A	UNKNOWN	FUSE CUTOUT
201588	11/15/2022 13:03	11/15/2022 14:00	0:56	0	05-Jerseyville Sub	2	B	MEMBER CAUSED	MEMBERS SIDE
201631	11/17/2022 21:00	11/17/2022 23:14	2:14	1				Vehicle	NO EQUIP CODE
201681	11/18/2022 11:00	11/18/2022 12:42	1:42	161	06-Nutwood Sub	1	ABC	PUBLIC ACCIDENTS, OTHER	POLE, DISTRIBUTION
201716	11/18/2022 17:55	11/18/2022 19:36	1:40	36	09-Staunton Sub	3	B	PUBLIC ACCIDENTS, OTHER	OCR OR SECTIONALIZER
201717	11/19/2022 10:29	11/19/2022 10:35	0:06	0	02-Bunker Hill Sub	1	C	UNKNOWN	NO EQUIP CODE
201734	11/21/2022 9:05	11/21/2022 10:48	1:43	2	14-Hornsby Sub	5	B	Animals	FUSE CUTOUT
201736	11/21/2022 11:32	11/21/2022 12:17	0:45	1	01-Brighton Sub	7	C	Animals	FUSE CUTOUT
201782	11/23/2022 3:56	11/23/2022 5:45	1:48	1	01-Brighton Sub	1	A	EQUIPMENT	TRANSFORMER STINGER WIRE
201785	11/23/2022 6:41	11/23/2022 7:58	1:16	1	11-Womac Sub	5	B	Animals	FUSE CUTOUT
201788	11/23/2022 10:53	11/23/2022 12:01	1:08	10	01-Brighton Sub	1	B	Machinery	POLE, DISTRIBUTION
201792	11/23/2022 15:41	11/23/2022 16:45	1:04	1	08-Rinaker Sub	3	A	UNKNOWN	TRANSFORMER, DISTRIBUTION
201833	11/24/2022 8:46	11/24/2022 10:00	1:13	5	11-Womac Sub	5	B	DECAY (Ground Level)	FUSE CUTOUT
201834	11/25/2022 9:18	11/26/2022 13:16	27:58:00	1				PUBLIC ACCIDENTS, OTHER	ANCHOR OR GUY
201843	11/25/2022 10:48	11/25/2022 11:57	1:08	12	09-Staunton Sub	3	A	Vehicle	NO EQUIP CODE
201846	11/25/2022 21:31	11/25/2022 22:20	0:48	1	11-Womac Sub	1	C	Animals	FUSE CUTOUT
201851	11/25/2022 21:54	11/25/2022 23:00	1:06	2	14-Hornsby Sub	7	B	UNKNOWN	FUSE CUTOUT
201885	11/26/2022 21:58	11/26/2022 23:30	1:31	7	01-Brighton Sub	1	C	UNKNOWN	FUSE CUTOUT
201899	11/27/2022 5:07	11/27/2022 7:14	2:07	26	09-Staunton Sub	7	C	UNKNOWN	OCR OR SECTIONALIZER
201945	11/27/2022 12:43	11/27/2022 15:47	3:03	26	09-Staunton Sub	7	C	TREES, OTHER	OCR OR SECTIONALIZER
201953	11/27/2022 14:26	11/27/2022 16:10	1:43	11	02-Bunker Hill Sub	5	A	UNKNOWN	FUSE CUTOUT
201963	11/27/2022 15:31	11/27/2022 15:49	0:18	30	09-Staunton Sub	7	A	TREES, OTHER	OCR OR SECTIONALIZER
201965	11/27/2022 15:35	11/27/2022 15:50	0:15	1	09-Staunton Sub	7	B	TREES, OTHER	OCR OR SECTIONALIZER
201790	11/28/2022 10:00	11/28/2022 15:10	5:10	1	09-Staunton Sub	1	A	MAINTENANCE	POLE, DISTRIBUTION
201789	11/28/2022 10:00	11/28/2022 15:10	5:10	2	09-Staunton Sub	1	A	MAINTENANCE	POLE, DISTRIBUTION
201970	11/28/2022 11:18	11/28/2022 12:03	0:44	2	11-Womac Sub	7	A	Animals	FUSE CUTOUT