

\*\* OCR, Feeders and Subs are included. Fuses, transformers and individuals are not. \*\*

**JULY 2021**

**07/01/2021 –**

9:18AM Butler – clear/calm; broken crossarm; had to take Butler sub down to fix, off 24mins

1:37PM Newbern – clear/calm; tree thru line; off 1 ½ hrs.

**07/02/2021 – 10:36AM**

Jerseyville – clear/calm; tree in line, off 3 ½ hrs

**07/05/2021 –**

11:09AM Jerseyville – clear/calm: birds, transformer fuse blown; off 2 ½ hrs.

2:00PM Womac – clear/calm; Power Supplier (tree thru line); off 1hr

2:03PM Honey Bend – clear/calm; Power Supplier (tree thru line); off 1hr

**07/09/2021 – 11:57pm**

Nutwood – storm– 2 trees thru 2 different lines in private; lines wrapped together; OCR #727; switch #289; off 12hrs.

**7/10/2021 –**

12:29am Brighton – storm; trees in line; off 6 hrs

2:26am Taylor Springs – storm; trees in line in private; got some members on then restored rest – total time off 7hrs.

2:43AM Bunker Hill – storm; power supplier; transmission tap; off 6hrs

3:02AM Witt – storm; trees in line, off 2 ½ hrs

5:07AM Brighton – storm; trees in lines; lighting arrestors URD (underground riser pole), off 9hrs.

11:29am Jerseyville – storm; trees in line, off 4hr

6:40pm Brighton – clear; calm: underground primary conductor; no cause found, off 1 ½hrs

**07/11/2021 – 11:10pm**

Nutwood – rain; tree thru line in private; breaker 715; off 5hrs

**07/13/2021 – 3:45am**

Taylor Springs – rain; trees thru line in private, off 5hrs.

**07/15/2021 – 6:54pm**

Nutwood – clear; calm: trees fell thru line in private, off 4 ½ hrs.

**07/22/2021 – 1:56PM**

Butler – clear; calm: mower hit guy wire flipping it into phases & wrapping together switch #363, off 1hr.

**07/23/2021 – 11:57PM**

Jerseyville – clear; calm - trees in line, OCR open; off 2hrs